



Split HeliRoll® Cluster

Are there damaged or missing HeliRoll® Clusters on your Commander?

JBT offers an economical, time-saving option when replacing these – our Split Service HeliRoll Cluster Kit.

Replacing damaged clusters on the convey system of a loader can be labor intensive. Our Split Service HeliRoll Cluster Kit allows the technician to simply replace the cluster without having to disconnect convey chains or remove and disassemble the HeliRoll shaft assembly.


Three simple steps:

- 1) Remove two rollers on opposite sides of the HeliRoll cluster from one another.
- 2) Cut or chisel through the aluminum cluster casting at these two locations to remove.
- 3) Install the clamshell halves of the new Split Service HeliRoll Cluster kit, and assemble with a 10mm wrench or socket.

JBT AeroTech part numbers:

624-4312-001 Left-hand Split Service HeliRoll Cluster kit

624-4312-002 Right-hand Split Service HeliRoll Cluster kit



www.jbtaerotechdirect.com

USA

7300 Presidents Drive
Orlando, FL 32809
USA
Phone: +1 407 851 3377
Fax: +1 407 850 2839
jbtaerotech.gse@jbtc.com

Spain

A-2, Km 34 400
28805 Alcalá de Henares
Madrid, Spain
Phone: +34 91 8775 880
Fax: +34 91 8775 881

UK

658 River Gardens
North Feltham Trading Est.
Feltham, London Heathrow
Middx, TW14 0RB, UK
Phone: +44 20 8587 0666
Fax: +44 20 8587 0660

Singapore

6 Loyang Lane, #03-00
Young Heng Industrial Building
Singapore 508920
Phone: +65 6542 9255
Fax: +65 6542 7493

Contact your Parts Representative today!

Orlando:
+1 407 850 4208
Toll Free: 1 800 821 3019

London:
+44 20 8831 2200

Madrid:
+34 91 8775 880

Singapore:
+65 6542 9272

