

Replace position indicator Alfa Laval valves

JBT SF&DS Amsterdam is globally providing high quality filling systems. These systems are known for their reliability and durability. The uptime of JBT SF&DS systems will provide our customers the competitive advantage over their competitors. It is our goal to improve this advantage in any way we can.

Is it open?

Sometimes the Inditop magnet connected to the actuator shaft will fail. This will result in incorrect feedback of the valve position.

A new design position indicator is selected and tested. Lifetime of the new component is multiple factors better than the current design, cost is lower and dimensions are smaller.

The installed position indicators will be replaced by the new design and new cables will be connected. This can all be done in a couple of hours. The result will be less unexpected disruptions of production and cleaning cycles.








Test setup:



Current Inditop:



New position indicator:

If you are interested in the new position indicator, contact your Area Customer Care manager for a proposal.

Please contact your JBT Customer Care manager for more information.

KitA14059-EN - 07•20 (298) Subject to change without notice

jbtc.com

JBT Food & Dairy Systems

Deccaweg 32 1042 AD Amsterdam The Netherlands Phone: +31.20.634.8911 Fax: +31.20.636.9754 info.ams@jbtc.com



Ordering Information

As part of JBT's commitment to your success, our wide range of upgrade kits are designed to give you maximum return on your original investment through increased performance and service life.

Please contact info.ams@jbtc.com for more information or to request a quote.

All JBT kits are subject to software/system compatibility and may change without previous notice.